

Contract # 50530

## Milestone Inspection – Phase 1

Prepared for the Board of Directors for the

### Pipers Run Condominium Association



+

This Report contains Milestone Inspection - Phase 1 for  
the Property with Address of:

19812 Gulf Blvd, Indian Shores, Florida 33785



March 24, 2025

## Purpose and Non-Conflict of Interest Disclosure

The purpose of this report is to certify the enclosed Milestone Inspection and Report was prepared for the above-mentioned association and is the result of work performed by Beryl Engineering & Inspection, LLC (Beryl). In addition, we certify that, to the best of our knowledge and belief:

1. All facts contained in this report are true and accurate.
2. Beryl has no present or prospective interest in the subject property of this report, and also has no personal interest with respect to the parties involved.
3. Beryl has no bias with respect to the subject property of this report or to the parties involved with this assignment.
4. Our engagement in this assignment was not contingent upon producing or reporting predetermined results.
5. Our compensation is not contingent on any action or event resulting from this report.
6. We have the knowledge and experience to generate accurate Milestone Inspection Report on all buildings contained within this report
7. We have performed a physical inspection of the subject risk(s) contained in this report.

Beryl conducted a Milestone Inspection – Phase I Per the Florida Statute Title XXXIII, Chapter 553, Section 899 and in conformance with the scope of work specified in SB 4-D & SB 154 – Building Safety, Dated May 26, 2022, and all other executed amendments to SB 4-D & SB 154, revisions Dated May 04, 2023, and, signed by the governor on June 09, 2023, passed by the state, as per the date of this report. The purpose of the Milestone Inspection – Phase I is to assess the subject property and determine the present condition of all of the major structural elements and components of the building(s), highlighting any deferred maintenance, commenting on on-site management issues as they relate to the care of the property, and documenting all observed deficiencies.

It is understood that Beryl did not evaluate the adequacy of the original construction system or materials used and does not ensure the adequacy and sufficiency of any documents or improvements reviewed. This assessment does not purport to encompass every report, record, permit, or other documentation relevant to the property and does not create or imply any guarantee of future building conditions or value.

The purpose of the property review was to assess the subject property and to determine the present condition of the following about the Building/Structural Components to include: Roofs, exteriors, breezeways, framing elements, load bearing, shear walls, foundation, and stairs.

We did not gain access to all areas, operate any specific equipment, or perform any tests. Beryl identified those areas that, in our opinion, require remedial work or restoration. This report is based on our professional opinion and field observations. It should be noted that site development drawings were not provided for our review.

---

# MILESTONE INSPECTION REPORT FORMS - STRUCTURAL BSIP INSPECTION FORM

Form EB18 – 2024

## MILESTONE INSPECTION REPORT FORM PHASE 1

### TABLE OF CONTENTS - Click on the subject or page number to advance to each section

Licensed Design Professional 1 Certification	Page 2
Licensed Design Professional 2 Certification	Page 3
1. Description of Structure	Page 4
2. Present Condition of Structure	Page 5
3. Inspections	Page 7
4. Supporting Data Attached	Page 7
5. Foundation	Page 8
6. Masonry Bearing Wall	Page 9
7. Floor and Roof System	Page 11
8. Steel Framing System	Page 16
9. Concrete Framing System	Page 17
10. Windows, Storefronts, Curtainwalls, and Exterior Doors	Page 19
11. Wood Framing	Page 21
12. Building Façade Inspection	Page 23
13. Special or Unusual Features in the Building	Page 23
14. Deterioration	Page 23
15. Unsafe Conditions	Page 24
16. Safe Occupancy Determination	Page 24
17. Summary of Findings	Page 25
18. Review of Existing Documents and Permit Records	Page 25
19. Definition of Terms	Page 26

# MILESTONE INSPECTION REPORT FORMS - STRUCTURAL BSIP INSPECTION FORM

Form EB18 – 2024

## MILESTONE INSPECTION REPORT FORM

### PHASE 1 Milestone Inspection

Initial Phase 1 Inspection Report       Amended Phase 1 Inspection Report as required after completion of any repairs.

*Note: All Required Fields Appear in Red*

### Licensed Engineer(s) or Architect(s) Responsible for the Milestone Inspection

Inspection Firm Name (if applicable): **Beryl Engineering & Inspection**

Inspection Engineer/Architect Name and License Number: **Leo Cannyn, PE-65994**

Address: **8202 N. Armenia Ave, Suite A, Tampa, FL 33604**

Telephone Number: **(813) 616-3301**

Assuming Responsibility for:  All       Portion - If Portion please list:

Inspection Commenced Date: **03/24/2025**      Inspection Completed Date: **03/24/2025**

Additional Inspection Firm Name (if applicable):

Additional Inspection Engineer/Architect Name:

Address:

Telephone Number:

Assuming responsibility for:  All       Portion – If portion please list:

Inspection Commenced Date:      Inspection Completed Date:

**NOTE:** Add pages as required to list all additional design professionals assuming responsibility for the Milestone Inspection or portions thereof. Each Design Professional must sign and seal their portion of the work in accordance with Florida Statutes.

Please check all that apply:

Substantial Structural Deterioration Observed; Phase 2 inspection is required

Reason to Believe a Dangerous Inaccessible Condition of Major Structural Component; Phase 2 inspection is required to complete Milestone Inspection of Inaccessible Conditions

Dangerous Condition Observed; Structural Evaluation is required; A Phase 2 Inspection is required

*\*A condition exists that the Milestone Inspector determines would need a Phase 2 Inspection or structural evaluation of the specific item identified or area in order to determine whether a dangerous condition exists.*

Immediate Dangerous Condition Observed; Notify Building and Fire Official; Structural Evaluation May be required, possible Shoring and a Phase 2 inspection is required

Maintenance Needed but does not raise to the level of Substantial Deterioration or Dangerous. Phase 1 Inspection Passes

Passed Phase 1 Inspections

Licensed Design  
Professional:

Engineer

Architect

Name: **Leo Cannyn**

License  
Number: **PE-69554**



Seal

**Click the button below to check if all required fields are completed.**

If they are not, you will be told which fields must be completed.

If they are, the signature box below will unlock, allowing you to sign and lock the form.

### **Check Required Fields**

I am qualified to practice in the discipline in which I am hereby signing,

Signature: \_\_\_\_\_ Date \_\_\_\_\_

This report has been based upon the minimum milestone inspection requirements as listed in *Chapter 18 of the Florida Building Code, Existing Building*. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

*See: General Considerations & Guideline*

**Supporting Data Attached:**

**Add Attachments**

Licensed Design  
Professional:

Engineer

Architect

Name: **Leo Cannyn**

License

Number: **PE-69554**



Seal

**Click the button below to check if all required fields are completed.**

If they are not, you will be told which fields must be completed.

If they are, the signature box below will unlock, allowing you to sign and lock the form.

### Check Required Fields

I am qualified to practice in the discipline in which I am hereby signing,

Signature:

Date

This report has been based upon the minimum milestone inspection requirements as listed in *Chapter 18 of the Florida Building Code, Existing Building*. To the best of my knowledge and ability, this report represents an accurate appraisal of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

**See: General Considerations & Guideline**

**Supporting Data Attached:**

Add Attachments

<b>1. DESCRIPTION OF STRUCTURE</b>		Add Attachments					
a. Name on Title: <b>Pipers Run Condominium Association Inc</b>							
b. Street Address: <b>19812 Gulf Blvd, Indian Shores, Florida 33785</b>							
c. Legal Description: <b>PIPER'S RUN CONDO</b>							
d. Owner's Name: <b>David Irwin</b>							
e. Owner's Mailing Address: <b>19812 Gulf Blvd, Indian Shores, Florida 33785</b>							
f. Email Address: <b>david1744@yahoo.com</b>		Contact Number: <b>(813) 474-6346</b>					
g. Folio Number of Property on Which Building is Located: <b>24-30-14-71822-000-0001</b>							
h. Building Code Occupancy Classification: <b>310.3 Residential Group R-2</b>							
i. Present Use: <b>0904 Condo Common Area Assn Own</b>							
j. General Description: <b>3 story multifamily residential</b>		Type of Construction: <b>Wood Frame</b>					
k. Square Footage: <table> <tr> <td>1. Total Building Area: <b>Approx. 13,600 sq ft</b></td> <td>Number of Stories: <b>3</b></td> </tr> <tr> <td>2. Building Footprint Area: <b>Approx. 8,040 sq ft</b></td> <td></td> </tr> </table>				1. Total Building Area: <b>Approx. 13,600 sq ft</b>	Number of Stories: <b>3</b>	2. Building Footprint Area: <b>Approx. 8,040 sq ft</b>	
1. Total Building Area: <b>Approx. 13,600 sq ft</b>	Number of Stories: <b>3</b>						
2. Building Footprint Area: <b>Approx. 8,040 sq ft</b>							
l. Name of the Condo or Coop Entity: <b>Pipers Run Condominium Association</b>							
m. Special Features:							
n. Describe any Additions to Original Structure:							
o. Approximate Distance to the Coast and Method Used to Determine Distance: <b>Approximately 300 ft via google earth.</b>							

**2. PRESENT CONDITION OF STRUCTURE****Add Attachments**

a. General Alignment (Note: ⓘ Good, Fair, Poor, Significant - Explain if significant):

1. Bulging:  Good  Fair  Poor  Significant

2. Settlement:  Good  Fair  Poor  Significant

3. Deflections:  Good  Fair  Poor  Significant

4. Expansion:  Good  Fair  Poor  Significant

5. Contraction:  Good  Fair  Poor  Significant

b. Portion Showing Distress (Note: Beams, Columns, Structural Walls, Floor, Roofs, Other):

Right rear concrete support beam under the balcony of unit 4 had excessive cracking, bulging and deflection. See Photos #65 - 68

## [2. PRESENT CONDITION OF STRUCTURE CONTINUED]

c. Surface Conditions – Describe general conditions of finishes, noting cracking, spalling, peeling, signs of moisture penetration and strains:

Cracking and exposed re-bar in a several locations throughout the parking garage.

See Photos #32 - 64

Deterioration and buckling of the wood siding throughout exterior. See Photos #83 - 99

d. Cracks – Note location in significant members. Identify crack size as HAIRLINE if Barely Discernible; FINE if less than 1 mm in width; MEDIUM if Between 1mm and 2 mm in Width; WIDE if Over 2mm

Location:  Hairline  Fine  Medium  Wide

See Above (Structure)

e. General Extent of Deterioration – Cracking or Spalling Concrete or Masonry, Oxidation of Metals; Rot or Borer Attack in Wood:

See Above (Structure)

f. Note Previous Patching or Repairs:

Left rear parking garage ceiling. See Photos #32,33

g. Nature of Present Loading Indicate Residential, Commercial, Other Estimate Magnitude:

None

h. Are there any other significant observations?  Yes  No

If Yes, Describe:

**3. INSPECTIONS**

Add Attachments



a. Date of Notice of Required Inspection: 03/24/2025

b. Date(s) of Actual Inspection: 03/24/2025

c. Name and Qualifications of the Individual Preparing Report:

**Leo Cannyn, PE-69554**

d. Description of Laboratory or Other Formal Testing, If Required, Rather than Manual or Visual Procedures:

**None**

e. Has the property record been researched for any current code violations or unsafe structure cases?

Yes  No

Explanation/Comments:

**Information not available from building department.**

**4. SUPPORTING DATA ATTACHED**

Add Attachments

Check if attached:

a. Sheets of written data:  Yes  No

b. Photographs:  Yes  No

c. Drawings or sketches:  Yes  No

d. Test reports:  Yes  No

## 5. FOUNDATION



a. Describe Building Foundation:

Concrete Pier and Beam

b. Is Wood in Contact or Near Soil?  Yes  No  N/A, Explain Below

c. Signs of Differential Settlement?  Yes  No

If Yes, Explain:

d. Describe Any Cracks, Separation, or Other Signs in the Walls, Column or Beams that Signal Differential Settlement:

None

e. Is water drained away from the foundation?

If No, Explain:  Yes  No

Left side gutter downspout discharged at the base of the foundation pier. See Photos #100 - 102

f. Is there additional Sub-Soil Investigation required?  Yes  No

If Yes, Describe:

## 6. MASONRY BEARING WALL – Indicate Good, Fair, Poor, or Significant on Appropriate Lines

Does this building have Masonry Bearing Walls? If yes, continue on. If no, skip to Section 7.

(Note:  Good, Fair, Poor, Significant)

Yes  No

a. Concrete Masonry Units:

Good  Fair  Poor  Significant  N/A

b. Clay Tile or Cotta Units:

Good  Fair  Poor  Significant  N/A

c. Reinforced concrete tie Columns:

Good  Fair  Poor  Significant  N/A

d. Reinforced Concrete Tie Beams:

Good  Fair  Poor  Significant  N/A

e. Lintel:

Good  Fair  Poor  Significant  N/A

f. Other Type Bond Beams:

Good  Fair  Poor  Significant  N/A

g. Masonry Finishes – **Exterior**:

1. Stucco:

Good  Fair  Poor  Significant  N/A

2. Veneer:

Good  Fair  Poor  Significant  N/A

3. Paint Only:

Good  Fair  Poor  Significant  N/A

4. Other:

Good  Fair  Poor  Significant  N/A

Explain:

h. Cracks – Note Beams, Columns, or Others, Including Locations (Description):

## [6. MASONRY BEARING WALL CONTINUED]

i. Spalling – In Beams, Columns, or Others, Including Locations (Description):

j. Rebar Corrosion – Check Appropriate Line:

1.  None Visible
2.  Minor – Patching will suffice
3.  Significant – Patching will suffice
4.  Significant – Structural repairs required

Describe:

k. Were samples chipped out for examination in spalled areas?

1.  No
2.  Yes – Describe color, texture, aggregate, general quality:

## 7. FLOOR AND ROOF SYSTEM

(Note:  Good, Fair, Poor, Significant)

Add Attachments



### a. Roof:

#### 1) Roof Pitch

Flat

Pitched

#### 2) Roof Structural Framing

- Wood
- Steel
- Concrete
- Unknown
- Other

If Other, Describe:

Unknown

#### 3) Roof Structural Framing Condition:

Good  Fair  Poor  Significant

#### 4) Roof Deck Material

<input type="checkbox"/> Concrete	<input type="checkbox"/> Bare steel deck
<input type="checkbox"/> Wood	<input checked="" type="checkbox"/> Other
<input type="checkbox"/> Structural concrete on steel deck	
<input type="checkbox"/> Non-structural / insulating concrete on steel deck	

Describe:

Unknown

#### 5) Roof Cladding Type

<input type="checkbox"/> Tile	<input type="checkbox"/> Single ply (Membrane)
<input checked="" type="checkbox"/> Asphalt shingles	<input type="checkbox"/> Metal
<input type="checkbox"/> Built-up roofing (BUR)	<input checked="" type="checkbox"/> Other

Describe:

Modified Bitumen

6) Roof Covering Condition

 Good  Fair  Poor  Significant

7) Note Water Tanks, Cooling Towers, Air Conditioning Equipment, Signs, Other Heavy Equipment and Condition of Support:

None

8) Note Types of Drains, Scuppers, and Condition:

Gutters and downspouts

9) Describe Parapet Construction and Current Condition:

N/A

10) Describe Mansard Construction and Current Condition:

 Good  Fair  Poor  Significant  N/A

11) Describe Any Roofing Framing Member with Obvious Overloading, Overstress, Deterioration, or Excessive Deflection:

None

12) Note Any Expansion Joint and Condition:

Good  Fair  Poor  Significant

**b. Floor System(s):**

1. Describe (Type of System Framing, Material, Spans, Condition, Balconies):

Condition:

Good  Fair  Poor  Significant

See Above (Structure)

2. Balcony Structural System

Edge and Building Face  
 Supported Cantilever  
 No Balcony

(If no balcony skip to number 7, Stairs and Elevators)

3. Balcony Exposure (if structure is on the coast)

Ocean facing  
 Non-ocean facing

There were two units with non-ocean facing balconies. Units 1 and 5.

## [7. FLOOR AND ROOF SYSTEM CONTINUED]

(Note:  Good, Fair, Poor, Significant)

## 4. Balcony Construction

Concrete

Steel framing with concrete topping

Wood

Other (define in narrative)

## 5. Balcony Condition Rating

Good

Fair (e.g., minor cracking, minor rebar corrosion – patching will suffice)

Poor (e.g., significant cracking, rebar corrosion requiring repairs)

Significant

## 6. Balcony Condition Description (e.g., Spalling, Cracking, Rebar Corrosion)

See Above (Structure)

## 7. Stairs and Elevators – Indicate location, framing system, material, and condition:

Stairs are traditional wood frame construction. Four Staircase: Two Staircases on the right side and two on the left side, front and rear.

The left and right front stairs were not secured to the concrete below. See Photos #103 - 112

## 8. Ramps – Indicate location, framing system, material, and condition:

None

## 9. Guardrails – Indicate type, location, and material

(If no Guardrail, skip to "c. Inspection")

Wood     Stainless Steel     Glass     None  
 Metal     Ungalvanized Steel     CMU Kneewall  
 Aluminum     Concrete Kneewall     Other \_\_\_\_\_

Describe any details:

Several Handrails were loose on the balconies and walkways. See Photos #

## 10. Guard Condition (define ratings depending on guard system)

Good     Fair     Poor     Significant, Describe:

Loose railings at least 3 locations. See photos #103, 105 - 112

## c. Inspection – Note exposed areas available for inspection, and where it was found necessary to open ceilings, etc. for inspection of typical framing members:

None

**8. STEEL FRAMING SYSTEM**[Add Attachments](#)

Steel Framing System Exists:  Yes  No (If no Steel Framing System, skip to section 9)

a. Full Description of System:

b. Exposed Steel – Describe condition of paint and degree of corrosion:

c. Steel Connections – Describe type and condition:

d. Concrete or Other Fireproofing – Describe any cracking or spalling and note where any covering was removed for inspection:

e. Identify any steel framing member with obvious overloading, overstress, deterioration or excessive deflection (provide location(s)):

f. Elevator Sheave Beams, Connections, and Machine Floor Beams – Note Column:

**9. CONCRETE FRAMING SYSTEM**

Add Attachments

Concrete Framing System Exists:  Yes  No (If no Concrete Framing System, skip to section 10)

a. Full Description of Structural System:

**Pier and Beam****b. Cracking:**

1.  Significant  Not Significant

2. Description of members affected location and type of cracking:

**See Above (Structure)****c. General Condition Description:****See Above (Structure)****d. Rebar Corrosion – Check Appropriate Line:**

1.  Non-Visible
2.  Significant – Patching will suffice
3.  Significant – Structural repairs required

Describe:

## [9. CONCRETE FRAMING SYSTEM CONTINUED]

e. Were samples chipped out for examination in spalled areas?

1.  No
2.  Yes – Describe color, texture, aggregate, general quality:

f. Identify any concrete framing member (e.g., slabs and transfer elements) with obvious overloading, overstress, deterioration (e.g., efflorescence at underside of slab or at base of column or wall) or excessive deflection (provide location(s)):

See Above (Structure)

(Note:  Good, Fair, Poor, Significant)

## 10. WINDOWS, STOREFRONTS, CURTAINWALLS AND EXTERIOR DOORS



a. Structural Glazing on the exterior envelope of threshold building:  Yes  No

1. Previous Inspection Date:

2. Description of Curtainwall Structural Glazing and adhesive sealant:

3. Describe Condition of System:

b. Exterior Doors:

1. Type:  Wood  Steel  Aluminum  Sliding Glass Door  Other  
(If Other, Describe):

Sliding Glass

2. Anchorage Type and Condition of Fasteners and Latches

Hinges.  
Dead Bolt.

3. Sealant Type and Condition of Sealant:  
 Good  Fair  Poor  Significant

## [10. WINDOWS, STOREFRONTS, CURTAINWALLS AND EXTERIOR DOORS CONTINUED]

4. Describe General Condition:

Good

5. Describe repairs needed:

**11. WOOD FRAMING**[Add Attachments](#)

Wood Framing System Exists:  Yes  No (If no Wood Framing System, skip to section 12)

a. Type – Fully describe if mill construction, light construction, major spans, trusses:

Second and third level were constructed with wood.

b. Indicate Condition of the Following:

1. Walls:

Unknown

2. Floors:

Unknown

3. Roof Member, Roof Trusses:

Unknown

c. Note Metal Fitting (i.e., Angles, Plates, Bolts, Splint Pintles, Other and Note Condition):

Unknown

d. Joints – Note if well fitted and still closed:

Good

## [11. WOOD FRAMING CONTINUED]

e. Drainage – Note accumulations of moisture:

See Above (Structure)

f. Ventilation – Note any concealed spaces not ventilated:

Good

g. Note any concealed spaces opened for inspection:

None

h. Identify any wood framing member with obvious overloading, overstress, deterioration, or excessive deflection:

See Above (Floor)

**12. BUILDING FACADE INSPECTION**[Add Attachments](#)

- a. Identify and describe the exterior walls and appurtenances on all sides of the building (cladding type, corbels, precast appliques, etc.):

**Wood Clading**

- b. Identify attachment type of each appurtenance type (mechanically attached or adhered):

**Mechanically attached**

- c. Indicate the condition of each appurtenance (distress, settlement, splitting, bulging, cracking, loosening of metal anchors and supports, water entry, movement of lintel or shelf angles or other defects):

**See Above (Structure)****13. SPECIAL OR UNUSUAL FEATURES IN THE BUILDING**

- a. Identify and describe any special or unusual features (i.e., cable suspended structures, tensile fabric roof, large sculptures, chimney, porte-cochere, retaining walls, seawalls, etc.):

- b. Indicate condition of special feature, its supports and connections:

**14. DETERIORATION**

- a. Based on the scope of the inspection, describe any structural deterioration and describe the extent of such deterioration.

**N/A**

## 15. UNSAFE CONDITIONS ▲

a. State whether unsafe or dangerous conditions exist, as these terms are defined in the Florida Building Code, where observed.  Yes  No

✓ By checking this box, the undersigned states that the inspections detailed in this report were performed with the primary objective of identifying potential structural issues. Other conditions may render a building unsafe, including, but not limited to, the existence of unsanitary conditions, inadequate maintenance, illegal occupancy, inadequate means of egress, or inadequate lighting and ventilation. If potentially unsafe conditions were observed, they will be noted, but the inspections were not intended to be a comprehensive assessment of whether any such conditions exist in the subject building.

## 16. SAFE OCCUPANCY DETERMINATION

a. Based on the results of the inspection, does the building or any portion of the building need to be vacated, secured, or access limited? If so, what portions of the building need to be vacated and how quickly do those portions need to be vacated, secured, or access limited?  Yes  No

Balcony unit 4.

See photos #118 - 121 for cost estimates.

[Add Attachments](#)

## 17. SUMMARY OF FINDINGS

The below Condition(s) were noted within this Phase 1 Inspection.

Indication of Dangerous Condition Observed

Actual Dangerous Condition Observed

Indication of Substantial Structural Deterioration Observed

Actual Substantial Structural Deterioration Observed

Indication of Need for Maintenance

Indication of Need for Repair

Indication of Need for Replacement

Inaccessible Condition of Structural Component

Phase 2 Inspection Required:

Yes  No

## 18. REVIEW OF EXISTING DOCUMENTS AND PERMIT RECORDS

It appears that unpermitted structural work has been performed as follows, and the Building Official has been notified:

Yes  No

If yes, describe unpermitted work:

Add Attachments

## 19. DEFINITIONS OF TERMS

**Good:** No Substantial Structural Deterioration and No Dangerous Condition Observed.

**Fair:** Indication of Substantial Structural Deterioration Observed and No Dangerous Condition Observed.

**Poor:** Actual Substantial Structural Deterioration Observed and No Dangerous Condition Observed.

**Significant:** Any Observation which is an Indication of Dangerous Condition or Actual Dangerous Condition.

**Major Structural Component.** Means a building's load-bearing elements, primary structural members, and primary structural systems.

**Substantial Structural Deterioration.** Means a condition that negatively affects a building's structural condition and integrity, or a major structural component whose condition meets the definition of Dangerous. The term does not include surface imperfections such as cracks, distortion, sagging, deflections, misalignment, signs of leakage, or peeling of finishes unless the licensed engineer or architect performing the phase one or phase two inspection determines that such surface imperfections are a sign of substantial structural deterioration.

**Unsafe conditions.** Buildings that are or hereafter become *unsafe*, insanitary or deficient because of inadequate means of egress facilities, inadequate light and ventilation, or that constitute a fire hazard, or are otherwise dangerous to human life or the public welfare, or that involve illegal or improper occupancy or inadequate maintenance, shall be deemed an *unsafe* condition. *Unsafe* buildings shall be taken down and removed or made safe as the *code official* deems necessary and as provided for in this code. A vacant building that is not secured against unauthorized entry shall be deemed *unsafe*. If an owner of the building fails to submit proof to the local enforcement agency that *repairs* have been scheduled or have commenced for substantial structural deterioration identified in a phase two milestone inspection report within the required timeframe, the local enforcement agency must review and determine if the building is unsafe for human occupancy.

**Dangerous.** Any building, structure or portion thereof that meets any of the conditions described below shall be deemed dangerous:

1. The building or structure has collapsed, has partially collapsed, has moved off its foundation or lacks the necessary support of the ground.
2. There exists a significant risk of collapse, detachment or dislodgment of any portion, member, appurtenance or ornamentation of the building or structure under permanent, routine, or frequent loads; under actual loads already in effect; or under wind, rain, flood, or other environmental loads when such loads are imminent.



**1** Front of the Building



**2** Right Side of the Building



**3** Rear of the Building



**4** Left Side of the Building



**5** Roof Overview



**6** Roof Overview



**7** Roof Overview



**8** Roof Overview



**9** Roof Overview



**10** Roof Overview



**11** Roof Overview



**12** Roof Overview



**13** Roof Overview



**14** Balcony Overview Unit 6



**15** Balcony Overview Unit 6



**16** Balcony Overview Unit 6



17 Balcony Overview Unit 6



18 Balcony Overview Unit 6



19 Balcony Overview Front



20 Walkway Overview



21 Stairs overview




22 Walkway Overview




23 Walkway Overview



24 Walkway Overview



**25** Stairs overview




**26** Stairs overview




**27** Stairs overview



**28** Stairs overview



**29** Stairs overview



**30** Stairs overview



**31** Garage Overview



**32** Rear Garage Ceiling Cracks Repairs



**33** Rear Garage Ceiling Cracks Repairs



**34** Right Middle Garage Cracking and exposed Re-Bar



**35** Damage to Left Rear Garage Beam From Flood Wall



**36** Damage to Left Rear Garage Beam From Flood Wall



**37** Damage to Left Rear Garage Beam From Flood Wall



**38** Damage to Left Rear Garage Beam From Flood Wall



**39** Right Middle Garage Cracking and exposed Re-Bar



**40** Right Rear Garage Cracking and exposed Re-Bar



41 Right Rear Garage Cracking and exposed Re-Bar



42 Right Rear Garage Cracking



43 Left Rear Garage Cracking and exposed Re-Bar



44 Left Rear Garage Cracking and exposed Re-Bar



45 Left Rear Garage Cracking and exposed Re-Bar



46 Rear Garage Pier Cracks and Exposed Re-Bar



47 Rear Garage Pier Cracks and Exposed Re-Bar



48 Rear Garage Pier Cracks



49 Rear Garage Pier Cracks



50 Rear Garage Pier Cracks



51 Middle Garage exposed re-Bar



52 Middle Garage exposed re-Bar



53 Rear Garage Beam Cracks



54 Rear Garage Beam Cracks



55 Rear Garage Beam Cracks



56 Left Side Garage Pier Cracks



57 Left Side Garage Pier Cracks



58 Left Side Garage Pier Cracks



59 Left Side Garage Exposed Re-Bar



60 Left Side Garage Exposed Re-Bar



61 Right Side Garage Pier Cracks



62 Right Front Garage Exposed Re-Bar



63 Right Front Garage Exposed Re-Bar



64 Right Front Garage Exposed Re-Bar



65 Right Front Garage Exposed Re-Bar



66 Right Front Garage Exposed Re-Bar



67 Right Rear Beam Cracking, Bulging and Rusting




68 Right Rear Beam Cracking, Bulging and Rusting



69 Right Rear Beam Cracking, Bulging and Rusting



70 Right Rear Beam Cracking, Bulging and Rusting




71 Loose Handrail Unit 6




72 Loose Handrail Unit 6



73 Loose Handrail Unit 8



74 Loose Handrail Unit 5



75 Loose and Cracked Handrail Unit 3



76 Loose and Cracked Handrail Unit 3



77 Garage Slab Cracks



78 Garage Slab Cracks




79 Garage Slab Cracks



80 Garage Slab Cracks



81 Right Rear Facia Deterioration



82 Right Front Facia Deterioration



83 Wood Siding Peeling and Buckling



84 Wood Siding Peeling and Buckling



85 Wood Siding Peeling and Buckling



86 Wood Siding Peeling and Buckling



87 Wood Siding Peeling and Buckling



88 Wood Trim Peeling and Buckling



**89** Wood Trim Peeling and Buckling



**90** Wood Trim Peeling and Buckling



**91** Rear Soffit Buckling



**92** Wood Siding Peeling and Buckling




**93** Wood Siding Deterioration




**94** Wood Siding Deterioration




**95** Wood Siding Deterioration



**96** Wood Siding Deterioration



**97** Wood Siding Deterioration



**98** Right Front Soffit Damage



**99** Right Front Soffit Damage



**100** Left Front Gutter Downspout Discharge at Pier Footing



**101** Left Front Gutter Downspout Discharge at Pier Footing



**102** Left Front Gutter Downspout Discharge at Pier Footing



**103** Right Front Stairs 4x4 Posts Not Secured to Slab



**104** Right Front Stairs 4x4 Posts Not Secured to Slab



105 Right Front Stairs 4x4 Posts Not Secured to Slab



106 Right Front Stairs 4x4 Posts Not Secured to Slab



107 Right Front Stairs 4x4 Posts Not Secured to Slab



108 Left Front Stairs 4x4 Posts Not Secured to Slab



109 Left Front Stairs 4x4 Posts Not Secured to Slab



110 Left Front Stairs 4x4 Posts Not Secured to Slab



111 Left Front Stairs 4x4 Posts Not Secured to Slab



112 Left Front Stairs 4x4 Posts Not Secured to Slab



## 113 Clogged Gutters and Debris on Roof



## 114 Clogged Gutters and Debris on Roof



## **115 Clogged Gutters and Debris on Roof**



## **116 Clogged Gutters and Debris on Roof**



## 117 Clogged Gutters and Debris on Roof

## 119 Cost Estimate

## **118 Cost Estimate**

## 120 Cost Estimate



FLAGSTONE BUILDERS  
1619 40TH AVENUE WEST  
HALMIE, FL 33736  
(727) 746-5271

Estimate # CLE 12048

Service	CLE HOME SERVICES	Date	08/01/2024						
Address		Date	PIPER'S HOME						
Contact / Associate	565-290-4983	Date	1619 40TH AVE. W. INIAN SHORES, FL 33785 1 <sup>ST</sup> AND 2 <sup>ND</sup> FLOOR FRONT PATIOS						
<b>Job Description:</b>									
<ul style="list-style-type: none"><li>Remove existing screen enclosure and since patio is done with work train replace using new fasteners using existing frames with new screen to be installed.</li><li>Remove and replace 12' total ft at both outside corners of fence 30' high (remove and replace using PT lumber not 2x4)</li><li>Remove and replace (2) 6"x6"x4' post and hurricane strapping as needed throughout no metal uplift posts</li><li>Remove and replace 1" x 2" trim about 48" to 24" paper face above screen frames</li><li>Remove and replace 2"x6" deck boards to 3"x6" floor patio only (1<sup>st</sup> floor is concrete with (2) 4x4 posts and 2x6 joists, 2nd floor is concrete with (2) 4x4 posts and 2x6 joists and 1x6 sub joists and install new through bolts.</li><li>Provide 1/4" for front patio for a safe installation to prevent</li><li>Provide 1/4" for front patio for a safe installation to prevent</li><li>Provide 1/4" for front patio for a safe installation to prevent</li><li>Provide 1/4" for front patio for a safe installation to prevent</li><li>Permit fees not included.</li><li>Painting is not included for new PT lumber installed.</li></ul>									
<b>PAYMENT TERMS:</b> \$16,000.00 due at signing and \$7,595.00 due upon completion. REMADE 1/2024 08/01/2024									
<table border="1"><thead><tr><th>Quantity</th><th>Amount</th></tr></thead><tbody><tr><td></td><td></td></tr><tr><td>Total:</td><td>\$28,595.00</td></tr></tbody></table>				Quantity	Amount			Total:	\$28,595.00
Quantity	Amount								
Total:	\$28,595.00								

**Important Conditions:**

**Scope of Work:** Company will provide to homeowner the services as described in the attached proposal which is hereby incorporated into this Contract as reference. Company will provide all services, materials, labor, tools, and equipment needed to complete or exceed the scope of work as described in the attached proposal. Company will provide services only to the extent and to the extent professional quality services according to acceptable industry standards and practices.

**Completion Dates:** Receipt of a 50% down payment is due upon signing of scope of work and prior to final scheduling for project initiation. Balance of payment is due upon completion of project. If circumstances beyond the control of the company prevent completion of the work completed until a new schedule is agreed upon by both parties.

**Change Orders:** Any deviation from the above Scope of Work involving a change in the scope of work or any additional costs will be assessed at the discretion of the company.

**Other Terms:** Homeowners who elect to use a financing option are 100% responsible for payments to company. Payment is the responsibility of the Homeowner and is due upon work completion.

## 121 Cost Estimate